

MSA | MS | MAV | PA | SW | SV

Magnetic Welding Angles

Your universal magnetic "henchman" for welding and assembly works. All magnetic angles are switchable and suitable for flat and round material. Only SW and SV 100 are not switchable.

SV 100, MAV 120 and PA 200 are stepless adjustable angles.



MS



SW



SV 100



MAV 120



PA 200



MSA

Features

- ✓ Easy positioning, adjusting and fixing of workpieces
- ✓ No deflection or influence of welding arc
- ✓ The contact areas of MS, MAV 120 and PA 200 are separately switchable
- ✓ The angle of MAV120 and PA200 have a light and accurate angle adjustment by quick release and scale



Technical data	Dimensions	Angle	Switchable	Use also for round material	Adhesive force	Weight	No.	Price
	[L×W×H] [mm]				[kg]	[kg]		
MSA I	110 x 30 x 95	45°/90°	Yes	Yes	40	0,7	45338	54,-
MSA II	150 x 35 x 130	45°/90°	Yes	Yes	75	1,4	45339	68,-
MS 2-80	153 x 38 x 153	90°	Yes *	Yes	55	1,2	48192	130,-
MS 2-90	195 x 46 x 195	90°	Yes *	Yes	120	2,7	18736	170,-
MAV 120	197 x 50 x 197	25° - 275°	Yes *	Yes	50	2,4	162	190,-
PA 200	240 x 41 x 240	22° - 270°	Yes *	Yes	90	1,6	60343	180,-
SW 200	200 x 50 x 200	90°	No	No	40	2,5	46504	110,-
SW 300	300 x 50 x 300	90°	No	No	60	4,0	46503	130,-
SV 100	190 x 50 + 150 x 50	30° - 270°	No	No	100	2,0	22318	130,-

* Every thigh is separately switchable